

Policy Update: Power Wheelchair Nonstandard Set Frames

Effective for dates of service on or after July 1, 2018, the following HCPCS codes for nonstandard seat frames for power wheelchairs are no longer separately reimbursable without certain requirements:

- E2340 - POWER WHEELCHAIR ACCESSORY, NONSTANDARD SEAT FRAME WIDTH, 20-23 INCHES
- E2341 - POWER WHEELCHAIR ACCESSORY, NONSTANDARD SEAT FRAME WIDTH 24-27 INCHES
- E2342 - POWER WHEELCHAIR ACCESSORY, NONSTANDARD SEAT FRAME DEPTH 20 OR 21 INCHES
- E2343 - POWER WHEELCHAIR ACCESSORY, NONSTANDARD SEAT FRAME DEPTH, 22-25 INCHES

For complete details, please refer to the following link.

<http://files.medi-cal.ca.gov/pubsdoco/bulletins/artfull/dme201806.asp#a4>